



FINAL VISUAL AND AIR CLEARANCE INSPECTION REPORT

Criterion

PROJECT #: 2002061

This letter is to certify that I performed a visual inspection of the asbestos abatement area(s) listed below and that:

- The area contains no visible dust or debris
- Air monitoring was performed in accordance with applicable regulations and/or the scope of work for this project
- The airborne asbestos level does not exceed the required and/or recommended re-occupancy standard

Phase Contrast Microscopy (PCM) pre-test samples were analyzed by:

Criterion Laboratories, Inc. - #100424 / 0000106 / _____ / _____ / _____
 AIHA-Accredited Laboratory City License # NIOSH 582 – Certified Microscopist (if applicable) AAR# (if applicable) City License #

Phase Contrast Microscopy (PCM) during project samples were analyzed by:

Criterion Laboratories, Inc. - #100424 / 0000106 / _____ / _____ / _____
 AIHA-Accredited Laboratory City License # NIOSH 582 – Certified Microscopist (if applicable) AAR# (if applicable) City License #

Phase Contrast Microscopy (PCM) post-test samples were analyzed by:

Criterion Laboratories, Inc. - #100424 / 0000106 / _____ / _____ / _____
 AIHA-Accredited Laboratory City License # NIOSH 582 – Certified Microscopist (if applicable) AAR# (if applicable) City License #

Transmission Electron Microscopy (TEM) post-test samples were analyzed by (if applicable):

EMSL Analytical, Inc. - #101048-0 N/A
 NVLAP/NIST-Accredited Laboratory

Building Name	Address		Contact		
Masterman School	1694 Spring Garden street phila, PA		Mr- Brian Joseph		
Description of Material	Location (room/floor/area)	Amount Of ACM	Visual Inspection Date	# of Clearance Samples Analyzed	Final Clearance Fiber Concentrations (F/CC)
Pipe Insulation	Room 9	1LF	1/14/20	1	20.01F/CC
Pipe Insulation	Room 302	1LF	1/14/20	1	20.01F/CC
Pipe Insulation	Room 304	1LF	1/14/20	1	20.01F/CC
Pipe Insulation	Room 313	1LF	1/14/20	1	20.01F/CC

Signature of Air Monitoring Technician: Paul scally

Date: 1/14/20

NOTE: To be completed for all projects outside of the City of Philadelphia and for non-TEM projects for the City of Philadelphia



Chain of Custody

Matrix Air
Analyte Asbestos
Analysis Type PCM
Container Cassette
Project 200204
Client School District of Philadelphia
Site Address Masterman MS/HS, 1699 Spring Garden Street,
Philadelphia, PA
Turnaround On-Site
Field Tech Paul Scally
Sample Notes
Chain of Custody Notes

Additional Analytes

Sample Number	Sample Type	Location	Received Condition	Date	Notes
200204-01-002-04-01	Area Sample	Basement Mens Restroom		1/14/2020	
200204-01-002-04-02	Post-Test	Room B-9 at riser		1/14/2020	
200204-01-002-04-03	Post-Test	Room 302 at work area		1/14/2020	
200204-01-002-04-04	Post-Test	Room 304 near desk		1/14/2020	
200204-01-002-04-06	Area Sample	Room 313 at screen		1/14/2020	
200204-01-002-04-07	Field Blank	Blank		1/14/2020	
200204-01-002-04-08	Field Blank	Blank		1/14/2020	

Sample Count 7

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	Ian Forster	1/14/2020	23:01	
Send Reports To	School District of Philadelphia	1/14/2020	23:01	
Samples Taken By	Paul Scally	1/14/2020	23:01	
Analyzed By	P. Scally	1/14/2020	23:01	
Received By	P. Scally	1/14/2020	23:01	
Relinquished By	P. Scally	1/14/2020	23:01	
Transported By	P. Scally	1/14/2020	23:01	