

Creek Cleaning Services

By Trash Free Waterways


For Turtle Creek Association

June 2026

Photo Documentation

Area of Responsibility

Turtle Creek from Wycliff Ave to
Maple Avenue



Supplemental work

- Removing wood and debris from under Lemmon Avenue Bridge
- Trimming William B Dean Park shoreline
- Trimming Maple Park

Items to be removed





Removal











Finished work





Under Lemmon Avenue Bridge before trimming



3510 hill and under Lemmon Ave Bridge trimmed



William B Dean Park shoreline trimmed



William B Dean park shoreline trimmed



Maple Park trimmed



Maple Park trimmed and wood collected



Monthly Trash Collection

Pond #1



Pond #1



Under Avondale Bridge



Pond #1



Pond #2



Trash collected in Pond #2



Pond #2



Pond #2



Trash collected in Ponds #1, #2, Stonebridge and Equality Park



Shoreline cleaning of Stonebridge Park







Trash collected from shoreline of Stonebridge Park



Above trash boom and walking bridge



Trash boom and walking bridge area



Trash boom cleaned



Trash collected from trash boom



Above walking bridge



William B Dean Park



William B Dean Park



William B Dean Park trash collected



Fallen trees in William B Dean Park



William B Dean Park – friendly Muscovies



North Hillwood




North Hillwood trash



North Hillwood trash



North Hillwood collected



South Hillwood



South Hillwood



South Hillwood trash collected



Hillwood cleaned



Cedar Springs Bridge area cleaned



Cedar Spring Bridge area trash collected




Creek south of Cedar Springs Bridge



South of Cedar Springs Bridge



Under Katy Trail Bridge cleaned



The Ravine




The Ravine trash collected



Under Fairmount Bridge



Maple Park trash and homeless



Maple Park graffiti and trash collected



Maple Park after cleaning

