

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 12/29/2016 @ 1:45 PM

Model Year: 2010	Vehicle Make: BMW	Vehicle Model: 528 I
VIN (scanned from vehicle): [REDACTED]		
VIN (manually entered or from DMV document): [REDACTED]		
License Plate: [REDACTED]	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 85000	

Overall Test Result

FAIL

Your vehicle failed the Smog Check inspection. Check your Owner's Manual to determine if the emission failure is repairable under the vehicle manufacturer warranty. Vehicles purchased new in California have an emission performance warranty for a minimum of 3 years or 50,000 miles that guarantees your vehicle passes the inspection. An emission parts warranty of 7 years or 70,000 miles covers certain high cost parts listed in the Owner's Manual. If your vehicle is a Partial Zero Emissions Vehicle (PZEV), the emission warranty extends to 15 years or 150,000 miles. The warranty for PZEV hybrid battery systems is 10 years or 150,000 miles. These warranties require the vehicle has not failed due to lack of scheduled maintenance, and other conditions specified in the vehicle's Owner's Manual. Warranty information by vehicle manufacturer is provided by the Bureau of Automotive Repair at www.bar.ca.gov.

BAR's Consumer Assistance Program (CAP) offers financial assistance with emission repairs and a monetary incentive to retire a vehicle from operation. If a warranty service or coverage problem arises, you may file a complaint with BAR. To learn more about CAP or to file a complaint, visit www.bar.ca.gov.

Visual Inspection: PASS Functional Inspection: FAIL

Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
PASS	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
PASS	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
PASS	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

<u>Result</u>		<u>Result</u>	
PASS	Liquid Fuel Leak Check	FAIL	OBD Bulb Check
FAIL	OBDII	PASS	Smoke Check

OBDII Monitors Not Ready

EGR and/or VVT System

Service Fault Codes

B0200 - ISO/SAE Reserved
C0300 - ISO/SAE Reserved
P0100 - Mass or Volume Air Flow Sensor "A" Circuit
P0101 - Mass or Volume Air Flow Sensor "A" Circuit Range/Performance
P0200 - Injector Circuit/Open
P0300 - Random/Multiple Cylinder Misfire Detected
U0100 - Lost Communication With ECM/PCM "A"

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 12/29/2016 @ 1:45 PM

Model Year: 2010	Vehicle Make: BMW	Vehicle Model: 528 I
VIN (scanned from vehicle): [REDACTED]		
VIN (manually entered or from DMV document): [REDACTED]		
License Plate: [REDACTED]	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 85000	

Smog Check Inspection Station Information

Station ID: RC [REDACTED]	Inspector Name/ID:	GROUP TWO FIVETWOONE/EO [REDACTED]
GROUP TWO TEST AND REPAIR DEALER C	Software Version/OIS ID:	6.7.993.0/CV010762
10949 NORTH MATHER BOULEVARD		
RANCHO CORDOVA, CA 95670		

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date

Inspector's Signature