Case Study: Harmony Place

- Cable and related safety issues
  - Low hanging cables (Cox, Verizon, and Dominion)
  - Loose cable and open pedestals
- Steps taken
  - CPRD Inspectors conducted site inspections
  - CPRD met on-site with Cox, Verizon, and Dominion
  - Cox, Verizon, and Dominion took action to fix the safety issues as much as possible
  - Citations issued for code violations
  - Address the low height of the private posts at certain units
- Remaining work
  - Management to follow-up regarding private posts
  - Cure code violations