

A close-up photograph of a car's instrument cluster. The background is a speedometer with white markings on a black face, showing numbers 50, 60, and 70. A yellow warning light, shaped like a tire with an exclamation mark inside, is illuminated. To the right, a red digital display shows 'P R N' in red. Overlaid on the right side of the image is white text.

POP QUIZ

Correct Answer:
B; Low Tire Air
Pressure

Light Maintenance - TPMS